

Aushärtezeiten

FIS SB Temperatur im Verankerungsgrund [°C]	Maximale Verarbeitungszeit FIS SB t_{work} [Min.]	Maximale Verarbeitungszeit FIS SB High Speed t_{work} [Min.]	Minimale Aushärtezeit FIS SB		Minimale Aushärtezeit FIS SB High Speed	
			t_{cure} [Std.]	[Min.]	t_{cure} [Std.]	[Min.]
> -20 – -15	-	60	-	-	24	-
> -15 – -10	60	30	36	-	8	-
> -10 – -5	30	15	24	-	-	180
> -5 – 0	20	10	8	-	-	120
> +0 – +5	13	5	4	-	-	60
> +5 – +10	9	3	-	120	-	45
> +10 – +20	5	2	-	60	-	30
> +20 – +30	4	1	-	45	-	15
> +30 – +40	2	-	-	30	-	-

1) Minimale Kartuschentemperatur +5°C